

5. Disconnect and remove 145-58801-58 hydraulic line assembly at the 300 x 4 union (located aft of the firewall, and connecting the 145-58801-62 line assembly connected to the selector valve).
6. Install the 145-51031-30 sump assembly in the 300 x 4 union connected to the 145-58801-62 line assembly.
7. Install the temporary placard on the instrument panel.
8. Return the 145-58019 regulator assembly to the factory.

NOTE: The hydraulic filter located in the reservoir assembly is not functioning when the power system is temporarily disconnected. Care should be taken that any hydraulic fluid added is especially clean oil.

JOHN W. CASEY
FIELD SERVICE MANAGER