



FIGURE 2-5. FRONT BEAM AND CENTER BEAM LIGHTENING HOLE REPAIR