

FIELD SERVICE BULLETIN

NO. 13

February 4, 1947

PUSH ROD AND VALVE ROCKER MODIFICATION

DELIVERED AIRPLANES AFFECTED:

NAV-4-11 through 34
36 through 42
44 through 47
50, 51, 54, 56, 60, 62, 64, 65, 68, 69, 70, 72, 74, 81, 83,
100, 192, 199, 207, 211, 214, 225, 228, 231, 234, 236,
239 through 242
244, 245, 249, 255, 259, 269, 271

This modification accomplished at the factory on all other airplanes.

This bulletin comprises the rework described in Continental Motors Corporation Service Bulletin No. E-113 dated November 29, 1946, copy attached.

This rework should be accomplished not later than the first engine overhaul.

JOHN W. CASEY
FIELD SERVICE MANAGER