

FIELD SERVICE BULLETIN

NO. 11

February 4, 1947

VALVE SPRING SPACER INSTALLATION

DELIVERED AIRPLANES AFFECTED:

NAV 4-11 through 22, 24, 26 through 29, 32, 33, 41, 42,
44 through 47, 62, 63, 192, 199

This modification accomplished at the factory on all other airplanes.

This bulletin comprises the rework described in Continental Motors Corporation Service Bulletin No. E-112 dated November 20, 1946, copy attached.

This rework should be accomplished not later than the first engine overhaul.

JOHN W. CASEY
FIELD SERVICE MANAGER